14.0 1		1	1	tic Terminal Passenger Elevator #1
Item	Price	Quantity	Total	Description
1		1	\$ -	Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
2		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new ca door, and associated components (track, hangers, gate switch – wate resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
3		1	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
4		2	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.
Total for A	tlantic Termi	inal Passengei	Elevator #1:	\$ -

Note: Atlantic terminal: Passenger elevator #1

Elevator has front opening
Elevator serves street level and ticket booth
Elevator has 36x84 single speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE Controller
Maxton valve
Elevator has guide shoes
Elevator has scavenger pump

	Pı	rice Sched	ule for Atlanti	ic Terminal Passenger Elevator #2
Item	Price	Quantity	Total	Description
1		1	\$ -	Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
2		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new car door, and associated components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
3		1	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
4		2	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.
Total for A	Atlantic Termi	nal Passengei	Elevator #1:	\$ -

Note: Atlantic terminal: Passenger elevator

Elevator has front opening
Elevator serves street level and ticket booth
Elevator has 36x84 single speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE Controller
Maxton valve
Elevator has Elsco 4" roller guides
Elevator has scavenger pump

		Price	Schedule f	for Baldwin Station Elevator
Item	Price	Quantity	Total	Description
1		6	\$ -	Replace rail guide shoe inserts
2		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
3		1	\$ -	Furnish and install new stainless steel car door panels.
4		2	\$ -	Furnish and install new stainless steel hoistway entrances complete: New SS 5WL door bucks and door panels, nickel/silver sill and sill extension. (door tracks, hangers, interlocks, stainless steel fascias, door closers, enforcer gibbs, Z brackets)
5		1	\$ -	Replace car door saddle with new nickel silver type.
6		1	\$ -	Replace defective or vandalized car fixtures: COP, lantern, with SS Mon
7		2	\$ -	Replace defective or vandalized hall fixtures: Hall buttons, arrival arrows, Pis.
Total for E	Bellmore Statio	on:		\$ -

Notes: Baldwin Stattion

Elevator has front opening only
Elevator serves strret level and platform level
Car door and hoistway doors has 36x84 2 speed side opening
This elevator has regular type GAL door pkg
Blain valve body
MCE controller HMC 2000
Elevator has scavenger pump
Elevator has guide shoes

		Price S	Schedule f	or Bellmore Station Elevator
Item	Price	Quantity	Total	Description
1		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
2		1	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
3		2	\$ -	Furnish and install new stainless steel hoistway entrances complete: New SS 5WL door bucks and door panels, nickel/silver sill and sill extension. (door tracks, hangers, interlocks, stainless steel fascias, door closers, enforcer gibbs, Z brackets)
4		1	\$ -	Replace defective or vandalized car fixtures: COP, lantern, with SS Moni
5		2	\$ -	Replace defective or vandalized hall fixtures: Hall buttons, arrival arrows, Pis.
Total for E	Bellmore Statio	on:		\$ -

Notes: Bellmore Stattion

Elevator has front opening only
Elevator serves strret level and platform level
Car door and hoistway doors has 36x84 single speed side opening
This elevator has regular type GAL door pkg
Blain valve body
MCE controller HMC 1000
Elevator has scavenger pump
Elevator has guide shoes

		Price S	cchedule	for Freeport Station Elevator
Item	Price	Quantity	Total	Description
1				Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
1		2	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
2		2	\$ -	
3		2	\$ -	Furnish and install new stainless steel hoistway entrances complete: New SS 5WL door bucks and door panels, nickel/silver sill and sill extension. (door tracks, hangers, interlocks, stainless steel fascias, door closers, enforcer gibbs, Z brackets)
4		2	\$ -	Replace defective or vandalized car fixtures: COPs, lantern, with SS Monitor type
5		2	\$ -	Replace defective or vandalized hall fixtures: Hall buttons, arrival arrows, Pis.
Total for Freeport Station Elevator:				\$ -

Notes: Freeport Station

Elevator has front and rear opening
Front serves street level
Rear serves platform level
The car door and hoistway door has 36x84 two speed side opening
MCE HMC 2000 controller
Maxton valve body
Gal water resistant door pkg
Elevator has guide shoes
Elevator has scavenger pump

		Price Scl	nedule for	Great Neck Station Elevator A
Item	Price	Quantity	Total	Description
1		1	خ	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
1		1	\$ -	Furnish and install new stainless steel car door panels; per car door
2		2	\$ -	opening.
3		2	\$ -	Furnish and install new stainless steel hoistway entrances complete: New SS 5WL door bucks and door panels, nickel/silver sill and sill extension. (door tracks, hangers, interlocks, stainless steel fascias, door closers, enforcer gibbs, Z brackets)
4			ć	Install new recessed LED cab lights to achieve 20 Foot Candles.
Total for G	Great Neck Sta	6 tion Elevator	(A):	\$ -

Note: Great Neck Station West bound Elevator

Elevator has front opening
Elevator serves street and platform level
Elevator has 36x84 two speed side car and hoistway doors
Elevator has GAL water resistant door pkg
MCE HMC 2000 controller
Elevator has roller guides
Elevator has Maxton valve body
Elevator has scavenger pump

2	2	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
	2	\$ -	
2			
	2	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
3	3	\$ -	Furnish and install new stainless steel hoistway entrances complete: New SS 5WL door bucks and door panels, nickel/silver sill and sill extension. (door tracks, hangers, interlocks, stainless steel fascias, door closers, enforcer gibbs, Z brackets)
			Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
4	1	\$ -	
5	6	\$ -	Install new recessed LED cab lights to achieve 20 Foot Candles.

Notes: Great Neck Station East bound Elevator

Elevator has front and rear opening
Front opening serves street level
Rear opening serves overpass level and platform level
Elevator has 36x84 two speed side car and hoistway doors
Elevator has GAL water resistant door pkg
MCE HMC 2000 controller
Elevator has roller guides
Elevator has Maxton valve body
Elevator has scavenger pump

		Price Sch	nedule for	Hicksville Station Elevator (A):
Item	Price	Quantity	Total	Description
				Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
1		1	\$ -	
2		2	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new car door, and associated components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
3		2	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
4		2	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.
5		1	\$ -	Remove the life jacket and install new rupture valve with electric contract
Total for H	icksville Stati	ion Elevator (<i>F</i>	A):	\$ -

Elevator has front and rear opening
Elevator is direct plunger type
Elevator has 2 stops, serving street and platform
Elevator has 36x84 two speed side car and hoistway doors
Elevator has GAL MOVFR water resistant door pkg
Motor Data plate info: 208 V, 60 Hz, 25 HP, 78.2 Amps
MCE HMC 1000 controller installed in December 2002
Elevator has Blain valve body
Elevator has scavenger pump
Elevator has guide shoes

		Price Sc	hedule for	· Hicksville Station Elevator (B)
Item	Price	Quantity	Total	Description
				Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
1		1	\$ -	
2		2	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new car door, and associated components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
3		2	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
4		2	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.
_				Remove the life jacket and install new rupture valve with electric contract
5		1	\$ -	
Total for F	licksville Statio	on Elevator (<i>F</i>	\):	\$ -

Elevator has front and rear opening
Elevator is direct plunger type
Elevator has 2 stops, serving street and platform
Elevator has 36x84 two speed side car and hoistway doors
Elevator has GAL MOVFR water resistant door pkg
Motor Data plate info: 208 V, 60 Hz, 25 HP, 78.2 Amps
MCE HMC 1000 controller installed in December 2002
Elevator has Blain valve body
Elevator has scavenger pump
Elevator has guide shoes

Price Schedule for Lynbrook Station Elevator A

Item	Price	Quantity	Total	Description
				Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
1		1	\$ -	
2		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new car door, and associated components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge,
3		1	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
4		2	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)
				Furnish and install new stainless steel hoistway door panels; per
5		2	\$ -	landing opening.
Total for L	.ynbrrok Stati	on Elevator (A	۸):	\$ -

Notes: Lynbrook Station Elevator A

Elevator has front opening
Elevator serves street level and platform level
Car door and hoistway door has 36x84 two speed side opening
GAL water resistant door pkg
MCE HMC 2000 controller
Maxton valve body
Elevator has guide shoes
Elevator has scavenger pump

Price Schedule for Lynbrook Station Elevator B

Item	Price	Quantity	Total	Description
				Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
1		1	\$ -	
2		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new car door, and associated components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
				Furnish and install new stainless steel car door panels; per car door
3		1	\$ -	opening.
4		2	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)
-			· ·	Furnish and install new stainless steel hoistway door panels; per
5		2	\$ -	landing opening.
Total for I	ynbrrok Statio	ın Flevator (A	J·	\$ -

Notes: Lynbrook Station: Elevator B

Elevator has front opening
Elevator serves street level and platform level
Car door and hoistway door has 36x84 two speed side opening
GAL water resistant door pkg
MCE HMC 2000 controller
Maxton valve body
Elevator has guide shoes
Elevator has scavenger pump

		Price So	chedule for	Queens Village Elevator (A)
Item	Price	Quantity	Total	Description
1		2	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new car door, and associated components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
2		1	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
3		2	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe
4 2 \$ -				Furnish and install new stainless steel hoistway door panels; per landing opening.
Total for C	Queens Village	Elevator (A):		\$ -

Elevator has front and rear opening
Elevator is direct plunger type
Elevator has 2 stops, serving street and platform
Elevator has center parting doors
Elevator has GAL MOVFR water resistant door pkg
MCE HMC 2000 controller
Elevator has Blain valve body
Elevator has scavenger pump
Elevator has roller guides

		Price S	chedule for	Queens Village Elevator (B)
Item	Price	Quantity	Total	Description
1		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new car door, and associated components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
2		1	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
3		2	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe
4		2	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.
Total for C	Queens Village	Elevator (B):		\$ -

Elevator has front opening
Elevator is direct plunger type
Elevator has 2 stops, serving street and platform
Elevator has center parting doors
Elevator has GAL MOVFR water resistant door pkg
MCE HMC 2000 controller
Elevator has Blain valve body
Elevator has scavenger pump
Elevator has roller guides

	Price Schedule for Rockville Center Station					
Item	Price	Quantity	Total	Description		
				Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II		
1		2	\$ -	-WATER RESISTANT TYPE). Install new safety edge, stainless steel toe		
2		2	\$ -	Furnish and install new stainless steel car door panels; per car door opening.		
3		2	\$ -	Furnish and install new stainless steel hoistway entrances complete: New SS 5WL door bucks and door panels, nickel/silver sill and sill extension. (door tracks, hangers, interlocks, stainless steel fascias, door closers, enforcer gibbs, Z brackets)		
4		2	\$ -	Replace defective or vandalized car fixtures: COPs, lantern, with SS Monitor type		
5		2	\$ -	Replace defective or vandalized hall fixtures: Hall buttons, arrival arrows, Pis.		
Total for F	Rockville Cente	er Station:		\$ -		

Notes: Rockville Station

Elevator has front and rear opening
Front opening serves stree levelt and platform level
Rear opening serves ticket booth and platform rear
Car door and hoistway doo has 36x84 two speed side opening
Gal water resistant door pkg
MCE HMC 2000 controller
Maxton valve body
This elevator has guide shoes
This elevator has scavenger pump

		Price	or Ronkonkoma Station - Elevator A	
Item	Price	Quantity	Total	Description
1		1	\$ -	Replace existing hydraulic jack. Remove old jack, pump out/clean the hole, install new 2013 ASME code compliant jack with schedule 80 PVC liner.
2		1	\$ -	Install new pit rupure valve with electrical contact, new shut off valve, necessary piping and replace hydraulic oil.
Total for R	onkonkoma :	Station Elevat	or (A):	\$ -

Ronkonkoma station:

Elevator A

Elevator has front opening
Elevator serves street level and overpass level
Elevator has 42x84 center opening car and hoistway doors
Elevator has GAL water resistant door pkg
MCE HMC 2000 controller
Elevator has roller guides
Elevator has scavenger pump

		Price	Schedule 1	for Ronkonkoma Station - Elevator C
Item	Price	Quantity	Total	Description
1		1	\$ -	Replace existing hydraulic jack. Remove old jack, pump out/clean the hole, install new 2013 ASME code compliant jack with schedule 80 PVC liner.
2		1	\$ -	Install new pit rupure valve with electrical contact, new shut off valve, necessary piping and replace hydraulic oil.
Total for R	onkonkoma :	Station Elevat	or (A):	\$ -

Ronkonkoma station:

Elevator C

Elevator has front opening
Elevator serves street level and overpass level
Elevator has 42x84 center opening car and hoistway doors
Elevator has GAL water resistant door pkg
MCE HMC 2000 controller
Elevator has roller guides
Elevator has scavenger pump

			Price Sc	hedule for Rosedale Station
Item	Price	Quantity	Total	Description
1		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car
				Furnish and install new stainless steel car door panels; per car door opening.
2		2	\$ -	
				Furnish and install new stainless steel hoistway entrances complete: New SS 5WL door bucks and door panels, nickel/silver sill and sill extension. (door tracks, hangers, interlocks, stainless steel fascias, door closers, enforcer gibbs, Z brackets)
3		2	\$ -	
4		1	\$ -	Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire
5		1	\$ -	Remove the life jacket and install new rupture valve with electric contract
6		1	\$ -	Replace defective or vandalized car fixtures: COP, lantern, with SS Monitor type
7		2	\$ -	Replace defective or vandalized hall fixtures: Hall buttons, arrival arrows, Pis.
Total for R	osedale Eleva	ator:		\$ -

Notes: Rosedale Station

Elevator has front opening
Elevator serves street level and platform level
Elevator has 42x84 two speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE HMC 2000 controller
Elevator has scavenger pump
Elevator has guide shoes
Maxton valve body

			Price So	chedule for Seaford Station
Item	Price	Quantity	Total	Description
1		1	<u>.</u>	Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
1		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install new car
2		2	\$ -	door, and associated components (track, hangers, gate switch – water
3		2	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
4		2	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.
5		2	\$ -	Replace defective or vandalized car fixtures: COPs, lantern, with SS Monitor type
				Replace defective or vandalized hall fixtures: Hall buttons, arrival arrows, Pis.
6		2	\$ -	
Total for S	eaford Elevate	or:		\$ -

Notes: Seaford Station

Elevator has front and rear opening
Front opening serves street level
Rear opening serves platform level
Car doors and hoistway doors has 36x84 two speed side opening
This elevator has regular type GAL door pkg
Maxton valve body
MCE controller HMC2000
Elevator has scavenger pump
Elevator has guide shoes

		Pric	e Schedule	e for Valley Stream Station
Item	Price	Quantity	Total	Description
				Replace rail guide shoe inserts
1		6	\$ -	
2		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
3		1	\$ -	Furnish and install new stainless steel car door panels; per car door opening.
4		2	\$ -	Furnish and install new stainless steel hoistway entrances complete: New SS 5WL door bucks and door panels, nickel/silver sill and sill extension. (door tracks, hangers, interlocks, stainless steel fascias, door closers, enforcer gibbs, Z brackets)
5		1	\$ -	Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
J		1	<u> </u>	Replace defective or vandalized car fixtures: COP, lantern, with SS
6		1	\$ -	Monitor type
7		2	\$ -	Replace defective or vandalized hall fixtures: Hall buttons, arrival arrows, Pis.
-	otal for Valley Stream Station:			\$ -

Notes: Valley Stream station:

Elevator has front opening
Elevator serves street level and platform level
Elevator has 36x84 two speed side car and hoistway doors
Regular type GAL door pkg
MCE HMC 1000 controller
Elevator has scavenger pump
Elevator has guide shoes
EECO valve body

			Price Sche	dule for Wanatgh Elevator
Item	Price	Quantity	Total	Description
1		1	\$	Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
				Car Door Package (Per Car Door Opening) – Furnish and install new car door, and associated components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe guards.
2		1	\$	-
				Furnish and install new stainless steel car door panels; per car door opening.
3		2	\$	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)
5		2	\$	Furnish and install new stainless steel hoistway door panels; per landing opening.
Total for \	Wantagh Stati	on:		\$ -

Wantagh Station Passenger elevator:

Elevator has front openings
Elevator serves street level and platform
Elevator has 36x84 single speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE Controller
Maxton valve
Elevator has Elsco 4" roller guides
Elevator has scavenger pump

		Price S	Schedule f	or Woodside Station - Elevator 415X
Item	Price	Quantity	Total	Description
1		2		Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe
2		2		Furnish and install new stainless steel car door panels; per car door opening.
3		1	\$ -	Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)
5		3	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.
6		1	\$ -	Furnish and install new hydraulic motor, pump, and Maxton valve body.
Total for V	Voodside Stati	on - Elevator	415X:	\$ -

Notes: Woodside station:

Elevator 415X

Elevator has front and rear opening
Elevator serves Street, LIRR platform A, and Mezzanine level.
Regular type GAL door pkg
Elevator has 36x84 two speed side car and hoistway doors
MCE 2000 controller
Maxton
Elevator has roller guides
Elevator has scavenger pump

		Price S	Schedule f	or Woodside Station - Elevator 416X
Item	Price	Quantity	Total	Description
				Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
1		1	\$ -	
Total for V	Voodside Stati	on - Elevator	416X:	\$

Notes: Woodside station:

Elevator 416X

Elevator has front opening
Elevator serves mezzanine level and platform level
Regular type GAL door pkg
Elevator has 36x84 two speed side car and hoistway doors
ESI controller
Maxton valve body
Elevator has guide shoes
Elevator has scavenger pump

	Price Schedule for Woodside Station - Elevator 417X						
Item	Price	Quantity	Total	Description			
				Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards			
1		1	\$ -				
Total for \	Noodside Stati	on - Elevator	· 417X:	\$ -			

Notes: Woodside station:

Elevator 417X

Elevator has front opening
Elevator serves mezzanine level and platform level
Regular type GAL door pkg
Elevator has 36x84 two speed side car and hoistway doors
ESI controller
Maxton valve body
Elevator has guide shoes
Elevator has scavenger pump

	Price Schedule for Wyandanch Garage Elevator #1						
Item	Price	Quantity	Total	Description			
				Degrease rails, and replace existing cwt shoes with roller guides. Rollers shall be with polyurethene on metallic hubs.			
1		1	\$ -				
				Replace Otis hoisting belts with the same model # item.			
2		1	\$ -				
Total for V	Vyandanch Ga	arage Elevato	r #1	\$ -			

Elevator serves 5 floors MRL AC Gearless Otis Gen 2 installed in 2015

		Price	Schedule	or Wyandanch Garage Elevator #2				
Item	Price	Quantity	Total	Description				
				Degrease rails, and replace existing cwt shoes with roller guides. Rollers shall be with polyurethene on metallic hubs.				
1		1	\$ -					
				Replace Otis hoisting belts with the same model # item.				
2		1	\$ -					
otal for V	Vyandanch Ga	arage Elevato	r #2	-				

Elevator serves 5 floors MRL AC Gearless Otis Gen 2 installed in 2015

Item	Price	Quantity	Total	Description
				Degrease rails, and replace existing cwt shoes with roller guides.
				Rollers shall be with polyurethene on metallic hubs.
1		1	\$ -	
				Replace Otis hoisting belts with the same model # item.
2		1	\$ -	
tal for W	/yandanch Ga	arage Elevato	r #3	\$

Elevator serves 5 floors MRL AC Gearless Otis Gen 2 installed in 2015

			Price	Schedule for Arch St #1
Item	Price	Quantity	Total	Description
1		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe
				Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)
2		3	\$ -	
Total for A	Arch St #1			\$

Elevator has front opening
Elevator serves 1,2,3 floors
Elevator has 38x84 single speed side car and hoistway doors
Elevator has regular type Dover door pkg
Tac 20 TK controller
Elevator has scavenger pump
Elevator has guide shoes

			Price	Schedule for Arch St #1				
Item	Price	Quantity	Total	Description				
1		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe				
				Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)				
2		2	\$ -					
Total for A	arch St #1							

Elevator has front opening
Elevator serves 1,2 floors
Elevator has 38x84 single speed side car and hoistway doors
Elevator has regular Dover door pkg
Tac 20 TK controller
Elevator has scavenger pump
Elevator has guide shoes

			Pri	ce Schedule for Eyegate						
Item	Price	Quantity	Total	Description						
1	\$ 10,000.00	1		Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe						
,	Å . C 000 00			Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards						
4	\$ 6,000.00	1		Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, door locks, stainless steel toe guard, spring closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)						
5	\$ 10,000.00	3								
Total for	Eyegate			\$ -						

Elevator has front opening
Elevator serves 1,2,3.
Elevator has 48x84 two speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE HMC 1000 controller
Elevator has scavenger pump
Elevator has guide shoes
Maxton valve body

			Pri	ce Schedule for HSF #1
Item	Price	Quantity	Total	Description
1		4	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved
2		4	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.
3		1	\$ -	Install new power unit with oil cooler, 80 SPM, with verically mounted dry motor ie: Mongrain LTPA. All hydraulic connections shall be threaded. Car speed 125 fpm
4		2	\$ -	Claddagh Series 15 Hydro Controller with Cloud Monitoring, and all necessary wiring.
				Replace existing cab with complete new utilizing 5WL ss for walls, and doors. Install new 1/4 epoxy floor and nickel silver saddle. GAL door package with Claddagh Hatch Latch zone lock. All new wiring. New Elsco model B roller guides with polyurethene rollers.
5		1	\$ -	
6		1	\$ -	Replace existing hydraulic jack. Remove old jack, pump out/clean the hole, install new 2013 ASME code compliant jack with schedule 80 PVC liner.
7		1	\$ -	Install new pit rupure valve with electrical contact, new shut off valve, necessary piping and replace hydraulic oil.
8		1	\$ -	Replace defective or vandalized car and hall fixtures:COP, Hall buttons, arrival arrows, Pis. With complete wiring.
Total for H	lillside Elevat	or #1:		\$

Elevator has front opening
Elevator serves 4 stops
Elevator has 38x84 single speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE HMC 1000 controller
Elevator has scavenger pump
Elevator has roller guides
Maxton valve body

			Prid	ce Schedule for HSF #3
Item	Price	Quantity	Total	Description
1		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe
2		2	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)
				Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
3		1	\$ -	
Total for H	Hillside #3:			\$ -

Notes: Hillside #3

Elevator has front opening
Elevator serves overpass level and platform level
Elevator has 42x84 single speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE HMC 2000 controller
Elevator has scavenger pump
Elevator has roller guides
Maxton valve body

			Pri	ce Schedule for HSF #4
Item	Price	Quantity	Total	Description
1		1	\$ -	Car Door Package (Per Car Door Opening) – Furnish and install all car door components (track, hangers, gate switch – water resistant type, clutch, linkages, gibbs, etc.) and door operator (with GAL MOVFR II –WATER RESISTANT TYPE). Install new safety edge, stainless steel toe
2		2	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved equal)
				Cab Floor Replacement – Remove existing flooring, repair platform and paint, install new sub floor consisting of two layers of 3/4" marine grade plywood, and provide all necessary fire proofing with fire retardant sheet on shaft way side, and install 3/8" epoxy floor. Replace all car saddles with Nickel-Silver. Provide stainless steel toe guards
3		1	\$ -	
Total for H	lillside #4:			\$ -

Notes: Hillside #4

Elevator has front opening
Elevator serves overpass level and platform level
Elevator has 42x84 single speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE HMC 2000 controller
Elevator has scavenger pump
Elevator has roller guides
Maxton valve body

			Price Scl	nedule for Jamaica Corp #1					
Item	Price	Quantity	Total	Description					
1		5	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved					
2		5	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.					
3		1	\$ -	Install new HW 200fpm, 3000 lbs capacity basement traction machine with rope gripper, replace all sheaves and cables,					
4		1	\$ -	Claddagh Series 3 Traction Controller with Cloud Monitoring, and all necessary wiring. New isolation transformer and shunt trip disconnect main line withh all new wiring. New EMR lights.					
5		1	\$ -	New CWT Elsco roller guides, Pit buffers, stop switches, lights. New governor and cable with wheelhouse stop switch, lights, all necessary guards and partitions in EMR, Pit and wheelhouse.					
				Replace existing cab with complete new utilizing 5WL ss for walls, and doors. Install new 1/4 epoxy floor and nickel silver saddle. GAL door package with Claddagh Hatch Latch zone lock. All new wiring. New Elsco model B roller guides with polyurethene rollers.					
6		1	\$ -						
7		1	\$ -	Replace defective or vandalized car and hall fixtures:COP, Hall buttons, arrival arrows, Pis. With complete wiring.					
Total for J	amaica Corp E	levator #1:		\$ -					

Elevator has front 2 speed openings
Elevator serves 5 stops
Elevator has 38x84 single speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE 1000 controller
Basement Traction with HW machine.
Elevator has roller guides

			Price Sc	nedule for Jamaica Corp #2						
Item	Price	Quantity	Total	Description						
1		5	\$ -	Hoistway Door Package (Per Landing/opening) – Furnish and install all new hoistway door components (door saddle – Nickel /Silver, door tracks, hangers, interlocks – water resistant type, stainless steel toe guard, door closers, enforcer gibbs, Z fire Brackets or LIRR approved						
2		5	\$ -	Furnish and install new stainless steel hoistway door panels; per landing opening.						
3		1	\$ -	Install new HW 200fpm, 3000 lbs capacity basement traction mack with rope gripper, replace all sheaves and cables,						
4		1	\$ -	Claddagh Series 3 Traction Controller with Cloud Monitoring, and all necessary wiring. New isolation transformer and shunt trip disconnect main line withh all new wiring. New EMR lights.						
5		1	\$ -	New CWT Elsco roller guides, Pit buffers, stop switches, lights. New governor and cable with wheelhouse stop switch, lights, all necessary guards and partitions in EMR, Pit and wheelhouse.						
				Replace existing cab with complete new utilizing 5WL ss for walls, and doors. Install new 1/4 epoxy floor and nickel silver saddle. GAL door package with Claddagh Hatch Latch zone lock. All new wiring. New Elsco model B roller guides with polyurethene rollers.						
6		1	\$ -							
7		1	\$ -	Replace defective or vandalized car and hall fixtures:COP, Hall buttons, arrival arrows, Pis. With complete wiring.						
Total for J	amaica Corp E	levator #1:		\$ -						

Elevator has front 2 speed openings
Elevator serves 5 stops
Elevator has 38x84 single speed side car and hoistway doors
Elevator has regular type GAL door pkg
MCE 1000 controller
Basement Traction with HW machine.
Elevator has roller guides

		V-	- u 1			and ital				1	inaniec an			uic.	d Repairs/	. 4. 65	0	#: a.a. V	1	1			Ontine V		
5	5 . O. /!!		ar 1	1		o.		Year 2	1				Year 3	1		F . O.		tion Yea			F 1 01		Option Y	ear 2	
Description	Est. Qty/Hrs	Hour	ly Rate		Total	Est. Qty		rly Rate	_	Total	Est. Qty		rly Rate		Total	Est. Qty		rly Rate		otal	Est. Qty		rly Rate	4	Total
ne (1) Engineer	40	\$		\$	-	40	\$	-	\$	-	40	\$	-			40	\$	-	\$		40	\$	-	\$	
ne (1) Adjustor/Lead																	_								
lechanic	2080	\$		\$	-	2080	\$	-	Ş	-	2080	\$	-	Ş	-	2080	\$	-	\$	-	2080	\$	-	\$	
nree (3) Resident																	_								
ull-Time Mechanics	6240	\$		\$	-	6240	\$	-	\$	-	6240	\$	-	\$	-	6240	\$	-	\$	-	6240	\$	-	\$	
Γ Labor Rate:																									
djustor/Lead Mechanic																									
•	400			,		400	ب ا		,		400	۱,		٨		400	ـ ا		,		400	_ ا			
.0 Regular work hours)	100	\$		\$	-	100	\$	-	\$	-	100	\$	-	\$	-	100	\$	-	\$	-	100	\$	-	\$	
Γ Labor Rate: Three (3)																									
esident Mechanic																									
	000	ے ا		۲.		000	ے ا		_ ا		000	ے ا		۸ ا		000	ے ا		۸ ا		000	ے ا		۲.	
.0 Regular work hours)	800	\$ 6		\$ \$	-	800 20	\$	-	\$	-	800	\$	-	\$	-	800 20	\$		\$	-	800	\$	-	\$ ¢	
Labor Rate: Engineer	20	\$		\$	-	20	Ş		\$	-	20	Ş	-	۶	-	20	Ş	-	\$	-	20	Ş	-	\$	
Labor Rate:																									
elper / Apprentice																									
	900	ے ا		\$		900	s	_	Ś		900	Ś	_	Ś		900	\$	_	ς		900	Ś		¢	
.0 Regular work hours) I Labor Rate:	900	Ş		Ş	-	900	٦		٦	-	900	٦		Ą	-	900	٦		γ	-	900	٦		Ş	
djustor/Lead																									
lechanic																									
Outside of ST & RDO)	500	خ ا		\$		500	\$	_	\$		500	Ś	_	\$		500	\$	_	Ś		500	\$	_	Ś	
T Labor Rate:	300	Ş		ې	-	300	۲		ې	-	300	۲		Ş	-	300	۲		γ	_	300	۲		Ą	
echanic (Outside of ST																									
RDO)	1850	خ		\$		1850	\$	_	Ś		1850	Ś	_	Ś		1850	\$	_	خ	_	1850	\$	_	ċ	
Labor Rate:	1830	۲		ڔ	_	1830	7		۲		1830	7		۲		1030	7		٧	_	1030	7		٦	
elper / Apprentice																									
Outside of ST & RDO)	500	ć		Ś	_	500	Ś	_	Ś		500	\$	_	Ś	_	500	\$	_	Ś	_	500	\$	_	\$	
district of 31 & NDO)	300	۲		۲		300			٦		300	7		٧		300	7		٧		300	7		۲	
arts & Material Mark-Up	\$70,000	(+/-)	%	\$	70,000.00	\$70,000) (+/-)	0.00%	\$	70,000.00	\$70,000) (+/-)	0.00%	\$	70,000.00	\$70,000	(+/-)	0.00%	\$ 7	70,000.00	\$70,000	(+/-)	0.00%	\$	7(
RRPL Insurance	1			\$	-	1	\$	-	\$	-	1	\$	-	\$	-	1	\$	-	\$, -	1	\$	-	\$	
OTAL	\$				70,000.00						\$				70,000.00	\$			7	70,000.00	\$				7(
															,										

1. It is estimated that parts and materials other than those included in the Monthly Maintenance portion of this Contract will cost the Railroad \$70,000 per year. Parts will be billed at your actual cost with no more than 10% material handling charge and profit. (Contractors will be required to supply all backup receipts to support their cost).

2 RRPL Insurance will be invoiced at the beginning of each contract year.

		Summary- Grand Total for all Items		
Item	Location			Cost
			·	
Α	Atlantic Term #1	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch; all doors	\$	-
В	Atlantic Term #2	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch; all doors	\$	-
С	Baldwin	Entrances, GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures	\$	-
D	Bellmore	Entrances, GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures	\$	-
E	Freeport	Entrances, GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures	\$	-
F	Great Neck (A)	Entrances, GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Floor, Cab lights	\$	-
G	Great Neck (B)	Entrances, GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Floor, Cab lights	\$	-
Н	Hicksville (A1)	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures, Floor, Rupture Valve	\$	-
I	Hicksville (B1)	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures, Floor, Rupture Valve	\$	-
J	Lynbrook (A)	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Floor	\$	-
K	Lynbrook (B)	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Floor	\$	-
L	Queens Village A	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch.	\$	-
М	Queens Village B	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch.	\$	-
N	Rockville Center	Entrances, GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures, Floor	\$	-
0	Ronkonkoma A	Jack, PVC liner, pit valves	\$	-
Р	Ronkonkoma C	Jack, PVC liner, pit valves	\$	-
Q	Rosedale	Entrances, GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures, Floor, Rupture Valve	\$	-
R	Seaford	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures, Floor	\$	-
S	Valley Stream	Entrances, GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Fixtures, Floors	\$	-
Т	Wantagh	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch.	\$	-
U	Woodside 415X	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch., Floor, Motor, Pump	\$	-
V	Woodside 416X	Floor	\$	-
W	Woodside 417X	Floor	\$	-
Х	Wyandanch Garage (1)	CWT roller guides & cables	\$	-
Υ	Wyandanch Garage (2)	CWT roller guides & cables	\$	-
Z	Wyandanch Garage (3)	CWT roller guides & cables	\$	-
AA	Arch Street 1	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch.	\$	-
AB	Arch Street 2	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch.	\$	-
AC	Eyegate/Jamaica (F&A)	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch.	\$	-
AD	Hillside Pass 1	Controller, Power unit, Cab, Entrances Jack-total mod	\$	-
AE	Hillside Pass 3	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch.	\$	
AF	Hillside Pass 4	GAL Door Package-operator, tracks, hangers, clutch, gibbs, edge, hatch latch.	\$	_
AG	Jamaica Corp (1)	Fixtures, Controller, Machine & cables-total mod	\$	_
AH	Jamaica Corp (2)	Fixtures, Controller, Machine & cables-total mod	\$	_
	34dica corp (2)	Times, especial official fractions & castles total mod	Ť	
em I	Grand Total for all Work from A thru AH			
Total f	or 5 Years of PM & Unschedulde Repairs:			
Grand	Total for all Work (Line 38 + 49)			

Contigency Funds for Additional work as requested and authorized ONLY.

LIRR makes no representations, guarantees or warranties that the amount of Any work constitutes the amount of work to be performed.

The Railroad has no obligation to pay the Contractor for any minimum level of service.

LOW LUMP SUM BID WILL BE BASED ON ITEM I. GRAND TOTAL FOR ALL WORK FROM A THRU AH.

The Railroad reserves the right to award the Contract based on Item I (without contigency) or based on Item II (with contigency).