


Good Neighbor Initiative Scorecard Results

Total Inspections 

7


Across all Categories 

B+



Pedestrian, Environment, and Livability

B



Site Upkeep, Cleanliness, and Housekeeping

B



Maintenance of additional site elements and Communication

A

7 Good Neighbor Initiative inspections conducted by the PAV Outreach Team

2 Rounds of stakeholder group surveys collected